

Light measurement



Solar Radiation Display and Integrator. for Use with Solar Sensors.

Code: [505-086](#)

Attributes: [Description](#) = Solar Radiation Display and Integrator

Standards:



Campbell Stokes Sunshine Recorder for latitudes 0-45 N or S. Includes 1 year supply of charts.

Code: [505-062](#)

Attributes: [Description](#) = Campbell Stokes Sunshine Recorder

Standards:



Accupar Ceptometer with 800 mm Probe Datalogger and RS 232 Interface. Battery Powered.

Code: [505-067](#)

Attributes: [Description](#) = Accupar Ceptometer with 800mm Probe Datalogger

Standards:



Digital Lux Meter

Code: [505-092](#)

Attributes: [Description](#) = Digital Lux Meter

Standards:



Light Measuring Unit (Luxmeter) with Sensor.

Code: [505-106](#)

Attributes: [Description](#) = Light Measuring Unit (Luxmeter)

Standards: