

General-purpose Thermometers



Maximum and Minimum Thermometer

Code: [82-5310](#)

Attributes: [Temperature Range °C = -40 to +50](#)

Standards:



Surface Thermometer

Code: [82-5311](#)

Attributes: [Temperature Range °C = 0 to +160](#)

Standards: