

Temperature measurement



Wall Thermometer Dual Range.

Code: [504-011](#)

Attributes: [Description = Wall Thermometer Dual Range](#)

Standards:



De-Luxe Inside/Outside Thermometer

Code: [504-020](#)

Attributes: [Description = De-Luxe Inside/Outside Thermometer](#)

Standards:



Minimum Thermometer -30 to +40 Deg. C Spirit Filled.

Code: [504-016](#)

Attributes: [Description = Minimum Thermometer -30 to +40 Deg. C Spirit Filled](#)

Standards:



Portable Soil Thermometer -10C to +50C.

Code: [504-024](#)

Attributes: [Description = Portable Soil Thermometer -10C to +50C.](#)

Standards:



Sheathed Earth Thermometer 300mm

Code: [504-032](#)

Attributes: [Description = Sheathed Earth Thermometer 300mm](#)

Standards:



Insulated Earth Thermometer 50mm

Code: [504-038](#)

Attributes: [Description = Insulated Earth Thermometer 50mm](#)

Standards:



Insulated Earth Thermometer 100mm

Code: [504-040](#)

Attributes: [Description](#) = Insulated Earth Thermometer 100mm

Standards:



Insulated Earth Thermometer 200mm

Code: [504-042](#)

Attributes: [Description](#) = Insulated Earth Thermometer 200mm

Standards:



Insulated Earth Thermometer 300mm

Code: [504-044](#)

Attributes: [Description](#) = Insulated Earth Thermometer 300mm

Standards:



Support Bracket for Earth Thermometers.

Code: [504-046](#)

Attributes: [Description](#) = Support Bracket for Earth Thermometers

Standards:



Electronic Inside/Outside Thermometer

Code: [504-019](#)

Attributes: [Description](#) = Electronic Inside/Outside Thermometer

Standards:



Laboratory Thermometer with Low Toxicity Filling

Code: [504-023](#)

Attributes: [Description](#) = Laboratory Thermometer with Low Toxicity Filling

Standards: